



Construction Advisory

Centennial ES – Mechanical Upgrades

Construction Update #5 – August 2017

Completion: Summer 2017

August-November (general scope):

1. Exterior site work – new transformer placement
2. Exterior – mechanical unit permanent screenwall

Note: Contractor in charge of building temperature until Chiller is operational.

Construction Scope

1. Boiler replacement
2. Chiller replacement
3. Domestic Water Heater replacement

For more information about the Denver Public Schools Bond Project, visit the Bond Project webpage at: <http://bond.dpsk12.org/>

What you need to know:

Parking	None
Pick up/Drop off	None.
Traffic	None.
Bike and pedestrian access	None.
Deliveries	Not during school hours.



Construction Advisory

Centennial ES – Mechanical Upgrades

Construction Update #5 – August 2017

Completion: Summer 2017

Utility disruption	Power outage for transformer replacement will not impact school operations.
Noise	None.
Smells	None.
Evacuation routes	None.
Daily routine/internal traffic patterns (lunch, recess, etc.)	None. Contractor activities in areas of academic operations to occur after school hours.